
**LEGEND**

- Sub-slab soil gas sample
- Indoor air sample
- Ambient air sample

U.S. EPA Environmental Response Team
 Scientific Engineering Response and Analytical Services
 Contract No. EP-W-09-031
 Work Assignment No. SERAS-130

FIGURE 1
EQP BUILDING SAMPLING LOCATIONS
CABO ROJO SITE
CABO ROJO, PR

PR-103



LEGEND

- Sub-slab soil gas sample
- Indoor air sample
- Ambient air sample



U.S. EPA Environmental Response Team
Scientific Engineering Response and Analytical Services
Contract No. EP-W-09-031
Work Assignment No. SERAS-130

FIGURE 2
S2A/B BUILDING SAMPLING LOCATIONS
CABO ROJO SITE
CABO ROJO, PR



Cll Pedro Albizu Campos

LEGEND

- Sub-slab soil gas sample
- Indoor air sample
- Ambient air sample



U.S. EPA Environmental Response Team
 Scientific Engineering Response and Analytical Services
 Contract No. EP-W-09-031
 Work Assignment No. SERAS-130

FIGURE 3
CRPDC BUILDING SAMPLING LOCATIONS
CABO ROJO SITE
CABO ROJO, PR



LEGEND

- Sub-slab soil gas sample
- Indoor air sample
- Ambient air sample



U.S. EPA Environmental Response Team
 Scientific Engineering Response and Analytical Services
 Contract No. EP-W-09-031
 Work Assignment No. SERAS-130

FIGURE 4
DEC BUILDING SAMPLING LOCATIONS
CABO ROJO SITE
CABO ROJO, PR



Legend

Sub-Slab Sampling Results
Tetrachloroethene ($\mu\text{g}/\text{m}^3$)

- Not Detected
- < 0.940
- 0.941 - 9.40
- 9.40 - 94.0
- 94.1 - 300
- 301 - 410
- 411 - 7400
- > 7401

7.5 Unit Number

Source Area

Map created using 2006 high resolution orthoimagery data from USGS, road data, site survey GPS data.
GPS data collected in Lat, Log, decimal degree, WGS 84

Map Creation Date: 17 April 2012

Coordinate system: GCS_WGS_1984
Datum: D_WGS_1984

Data: g:\airteam\SERAS\arcview\projects\00-130
MXD file: g:\airteam\SERAS\arcinfo\projects\SER00130_Cabo_Rojo\PCE_Sampling_Result_Map_fig6

Note: Unit 2 (DEC Building) does not appear on the figure, as it is not in the area of concern sampled during both mobilizations.

U.S. EPA Environmental Response Team
Scientific Engineering Response and Analytical Services
Contract No. EP-W-09-031
Work Assignment No. SERAS-130

FIGURE 6
TETRACHLOROETHENE RESULTS - FEBRUARY AND MARCH 2012
CABO ROJO SITE
CABO ROJO, PR

